

Need an amazing tutor?

www.teachme2.com/matric



Collected and collated by

teachme2



basic education

Department:
Basic Education
REPUBLIC OF SOUTH AFRICA

NATIONAL SENIOR CERTIFICATE

GRADE 12

MECHANICAL TECHNOLOGY: WELDING AND METALWORK

NOVEMBER 2021

MARKING GUIDELINES

MARKS: 200

These marking guidelines consist of 23 pages.

QUESTION 1: MULTIPLE-CHOICE QUESTIONS (GENERIC)

- | | | |
|-----|---------|------------|
| 1.1 | B ✓ | (1) |
| 1.2 | A ✓ | (1) |
| 1.3 | D ✓ | (1) |
| 1.4 | A / C ✓ | (1) |
| 1.5 | A ✓ | (1) |
| 1.6 | C ✓ | (1) |
| | | [6] |

QUESTION 2: SAFETY (GENERIC)**2.1 First-aid applications to an open wound:**

- Use surgical gloves. ✓
- Do not remove anything that is stuck to the wound. ✓
- Never use sticky plaster on the wound. ✓
- Cover the wound with a clean, lint-free cloth. ✓
- Avoid using any oily substances or lotions on wounds. ✓
- If necessary, cool wounds with cold water. ✓
- Apply pressure to prevent blood loss if necessary. ✓
- Avoid contact with blood from patient. ✓
- If the wound is on your arm, raise the arm above your head to stop the bleeding. ✓

(Any 2 x 1) (2)**2.2 Surface grinder: (Already switched on)**

- Never leave the grinder unattended. ✓
- Switch off the machine when leaving. ✓
- Don't try to stop revolving emery wheel with your hand. ✓
- Don't adjust the machine while working. ✓
- Don't open any guard while the machine is on. ✓
- Do not force the grinding wheel on to the work piece. ✓
- Approach the work piece slowly and evenly. ✓
- Don't clean the machine while working. ✓
- Do not put hands near the work piece when grinder is in motion. ✓
- Don't clean or adjust the machine while working. ✓
- Check for oil on the floor while working (spilling of cutting fluid on floor while working) ✓
- Check that the grinding wheel is running evenly. ✓

(Any 2 x 1) (2)**2.3 Gauges calibrated:**

- To ensure accurate readings. ✓
- To prevent overloading. ✓

(Any 1 x 1) (1)**2.4 Finger protectors' hazards on power driven guillotines:**

- The finger protector prevents the hazards of getting the fingers cut by the blades. ✓
- To be crushed by the hold-downs. ✓

(2)

2.5 **Welding or flame cutting operation safety:**

- An operator has been instructed on how to use the equipment safely. ✓
- A workplace is effectively partitioned off. ✓
- An operator uses protective equipment. ✓
- Ensure that all equipment is in safe working condition. ✓
- Ensure that there are no flammable materials around the welding area. ✓
- Weld area must be well ventilated. ✓
- Fire extinguisher must be in close proximity. ✓

(Any 2 x 1) (2)

2.6 **Workshop layout:**

Product layout. ✓

(1)

[10]

QUESTION 3: MATERIALS (GENERIC)**3.1 File test:**

3.1.1 Difficult ✓ (1)

3.1.2 Easy ✓ (1)

3.1.3 Difficult ✓ (1)

3.2 Heat treatment:

A. – Grain growth. ✓

B. – Recrystallisation. ✓

C. – Recovery. ✓

(3)

3.3 Bending test:

- Bend the test piece through a specific angle or around a mandrel or bar, ✓ having a defined radius, ✓ until a rupture in the metal occurs. ✓
- Place the material in a vice and bend it ✓ then observe ✓ the ductility of the material. ✓

(Any 1 x 3)

(3)

3.4 Purpose of case hardening:

Creates a hard surface ✓ with a tough core. ✓

(2)

3.5 Quenching media for hardening:

- Water ✓
- Brine (saltwater) ✓
- Oil ✓
- Soluble oil and water ✓
- Nitrogen air-infused air ✓

(Any 3 x 1)

(3)

[14]

QUESTION 4: MULTIPLE-CHOICE QUESTIONS (SPECIFIC)

4.1	B ✓	(1)
4.2	B ✓	(1)
4.3	D ✓	(1)
4.4	C ✓	(1)
4.5	D ✓	(1)
4.6	A ✓	(1)
4.7	A ✓	(1)
4.8	B ✓	(1)
4.9	C ✓	(1)
4.10	B ✓	(1)
4.11	C ✓	(1)
4.12	B ✓	(1)
4.13	A ✓	(1)
4.14	D ✓	(1)
		[14]

5.4 **Hand tools: (Due to the large number of alternatives, marker discretion must be used - discuss with IM).**

- Hand saws ✓
- Chisels ✓
- Plane ✓
- Handdrill and drill bits ✓
- Steel measuring tape ✓
- Straight edge ✓
- Compass ✓
- Trammel pins ✓
- Carpenter's square ✓
- Protractor ✓
- Chalk line ✓
- Steel rule ✓
- Hammers ✓
- Centre punch ✓
- Callipers ✓
- Scribe ✓
- Combination square ✓
- Spirit level ✓
- Trammel ✓

(Any 3 x 1) (3)

5.5 **Template loft machines: (Due to the large number of alternatives, marker discretion must be used - discuss with IM).**

- Circular saw ✓
- Planer ✓
- Drilling machine ✓
- Jig saw ✓
- Sanding machine ✓
- Shears for cutting cardboard ✓
- Welding machine ✓
- Angle grinder ✓
- Bench grinder ✓
- Guillotine ✓
- Cut-off power saw ✓

(Any 2 x 1) (2)

[23]

QUESTION 6: TOOLS AND EQUIPMENT (SPECIFIC)**6.1 Operating principles of a resistance welding machine:**

- Current flows through a resistance to fuse plates together. ✓
- Two copper electrodes are pressed against the plates. ✓
- Heavy current is passed between the electrodes. ✓
- High resistance causes intense heat at the point. ✓
- The two plates melt and fuse together, forming a weld nugget or spot weld. ✓

(5)

6.2 Arc welding:

- 6.2.1 A. Arc welding machine / Power source / inverter. ✓
B. Earth clamp / “skelm” ✓
C. Electrode / Rod / welding rod ✓
D. Electrode holder ✓

(4)

- 6.2.2
- Holds the electrode. ✓
 - Insulate the person welding ✓
 - Provide current to the electrode ✓
 - Used with electrode to weld ✓

(Any 1 x 1)

(1)

6.3 Cutting of threads:

- Secure the die in die wrench/stock ✓ and set die square to the shaft to be cut. ✓
- Rotate the die through half a turn in a clockwise direction ✓ to cut the thread and then turn back a quarter of a turn ✓ to break off waste.
- Continue process until the die has reached the required length of thread ✓ and adjust the centre and side screws until desired thread fit is achieved. ✓

(6)

6.4 Advantages of using a punch machine:

- Can punch holes faster. ✓
- Punch various hole profiles ✓
- Less effort is needed ✓

(Any 1 x 1)

(1)

Pyramid rollers

- 6.5
- Rolling sheet metal. ✓
 - Used to roll round bars ✓

(Any 1 x 1)

(1)

[18]

QUESTION 7: FORCES (SPECIFIC)**7.1 Beams:****7.1.1 Calculating reactions:****Taking moments about RL:**

$$\begin{aligned}
 RR \times 10 &= (80 \times 3) + (60 \times 5) + (100 \times 7) \\
 &= 240 + 300 + 700 \\
 RR &= \frac{1240}{10} \\
 &= 124 \text{ N}
 \end{aligned}$$

Taking moments about RR:

$$\begin{aligned}
 RL \times 10 &= (100 \times 3) + (60 \times 5) + (80 \times 7) \\
 &= 300 + 300 + 560 \\
 RL &= \frac{1160}{10} \\
 &= 116 \text{ N}
 \end{aligned}
 \tag{8}$$


7.1.2 Calculating bending moments:**Bending moments at B, C and D:**

$$\begin{aligned}
 BM_B &= (116 \times 3) \\
 &= 348 \text{ Nm}
 \end{aligned}$$

$$\begin{aligned}
 BM_C &= (116 \times 5) - (80 \times 2) \\
 &= 420 \text{ Nm}
 \end{aligned}$$

$$\begin{aligned}
 BM_D &= (116 \times 7) - (80 \times 4) - (60 \times 2) \\
 &= 372 \text{ Nm}
 \end{aligned}
 \tag{3}$$

7.1.3 Bending moment diagram:



NOTE: Draw the bending moment diagram to scale for marking purposes.

(7)

7.2 Stress and Strain:**7.2.1 Diameter of a bar:**

$$\sigma = \frac{F}{A}$$

$$A = \frac{F}{\sigma} \quad \checkmark$$

$$= \frac{40 \times 10^3}{20 \times 10^6} \quad \checkmark$$

$$= 2 \times 10^{-3} \text{ m}^2 \quad \checkmark$$

$$A = \frac{\pi D^2}{4}$$

$$D = \sqrt{\frac{4A}{\pi}} \quad \checkmark$$

$$= \sqrt{\frac{4(2 \times 10^{-3})}{\pi}} \quad \checkmark$$

$$= 0,05046265 \text{ m} \quad \checkmark$$

OR

$$= 50,46 \text{ mm} \quad \checkmark$$

(6)

7.2.2 Strain:

$$\varepsilon = \frac{\sigma}{E}$$

$$\varepsilon = \frac{20 \times 10^6}{90 \times 10^9} \quad \checkmark$$

$$= 0,22 \times 10^{-3} \quad \checkmark$$

(2)

7.2.3 Change in length:

$$\varepsilon = \frac{\Delta L}{OL}$$

$$\Delta L = \varepsilon \times OL \quad \checkmark$$


$$= (0,22 \times 10^{-3}) \times 2 \quad \checkmark$$

$$= 0,44 \times 10^{-3} \text{m}$$

$$= 0,44 \text{mm} \quad \checkmark \quad (3)$$

7.3 Stress and strain diagram:A: Limit of proportionality \checkmark B: Elastic limit \checkmark C: Yield point \checkmark D: Maximum stress \checkmark E: Break stress \checkmark

(5)

7.4 Simple frame:**7.4.1 Vector/Force diagram:**

(5)

7.4.2 **Magnitude and nature of force:**

Member	Force	Nature
AD	250 kN ✓	Strut ✓
BD	433 kN ✓	Strut ✓
CD	216 kN ✓	Tie ✓

(6)
[45]

QUESTION 8: JOINING METHODS (INSPECTION OF WELDS) (SPECIFIC)**8.1 Arc welding aspects:**

- Rate of rod burning and the progress of the weld ✓
- Amount of penetration and fusion. ✓
- Observe for welding defects while welding ✓
- The sound of the arc indicating correct current and voltage for the particular weld. ✓
- Angle of electrode. ✓
- Arc length. ✓
- Size of molten pool while welding ✓

(Any 3 x 1) (3)**8.2 Centreline cracks:**

- Aiming at width to depth ratio of 1:1. ✓
- Decreasing the current to prevent excess penetration. ✓
- Decreasing welding voltage ✓
- Slowing travel speed to achieve a flat to convex weld surface. ✓
- Use clamping device. ✓
- Pre – Heating ✓
- Use of correct electrode ✓

(Any 2 x 1) (2)**8.3 Welding defects:****8.3.1 Lack of fusion:**

- Travel speed is too slow. ✓
- Wide weld joint. ✓
- Weld current too low. ✓
- Too big weaving action. ✓
- Included angle not correct. ✓
- Contaminated parent metal surface ✓
- Weld metal not permitted to roll in front of arc. ✓
- Arc not kept on leading edge of molten pool. ✓
- Travel speed too fast. ✓
- Excessive mill scale (iron oxide) ✓

(Any 2 x 1) (2)

8.3.2 Porosity:

- Contaminated weld surface. ✓
- Wet or dirty electrodes. ✓
- Shielding gas supply is interrupted. ✓
- Welding in windy conditions. ✓

(Any 2 x 1) (2)**8.3.3 Incomplete penetration:**

- Welding current too low. ✓
- Welding speed too fast. ✓
- Incorrect electrode angle. ✓
- Poor joint preparation. ✓
- Insufficient root gap. ✓
- Electrode too big. ✓
- Too long arc. ✓
- Contaminated weld surface. ✓

(Any 2 x 1) (2)**8.4 Setting oxy-acetylene torch flame to a neutral flame:**

- Open acetylene torch valve $\frac{1}{4}$ turns or less and ignite. ✓
- Adjust the acetylene torch valve further until the black smoke disappears. ✓
- Open oxygen torch valve until the flame is no longer burning yellow. ✓
- Inner cone of the flame must be rounded. ✓

(Any 3 x 1) (3)**8.5 Guided bend test:**

- Specimen is placed across the supports of the die. ✓
- Apply force to the specimen to bend into shape of the die. ✓
- Determine the percentage of elongation of the weld metal. ✓

(3)**8.6 Free bend test:**

- Determine the ductility of the weld. ✓
- Determine the ductility of the heat – affected area adjacent to the weld. ✓
- Determine the percentage of elongation ✓

(Any 2 x 1) (2)**8.7 Types of dye:**

- Type A: Fluorescent that emits visible light when viewed using a Black light. ✓
- Type B: Brightly coloured liquid dyes that can be inspected in regular light. ✓

(2)

8.8 Nick-break test:

- Determines internal ✓ quality of the weld metal. ✓
- Reveals internal defects ✓ such as slag inclusions, porosity and lack of fusion. ✓

(Any 1 x 2) (2)
[23]

QUESTION 9: JOINING METHODS (STRESS AND DISTORTION) (SPECIFIC)**9.1 Causes of residual stress in welds:**

- Heat present in the weld. ✓
- Qualities of parent metal, filler rod or electrode. ✓
- Shape and size of weld. ✓
- Number of successive weld runs. ✓
- Comparative weight of weld and parent metal. ✓
- Type of welding joint used. ✓
- Welding method used to mitigate stress and distortion. ✓
- Type of structure of neighbouring joints. ✓
- Freeness of joint to be able to expand and contract. ✓
- Rate of cooling. ✓
- Stresses already present in the parent metal. ✓

(Any 2 x 1) (2)**9.2 Factors of cooling rate:**

- Size of work piece. ✓
- Weld thickness. ✓
- Thermal conductive properties of parent metal. ✓

(Any 3 x 1) (3)**9.3 Effect of cold working:**

- The effect of cold working is to break down the crystal structure ✓
elongating the grains. ✓
- An elongated and distorted crystal structure of this kind gives the
metal greater hardness ✓ and tensile strength. ✓
- Reduces ductility. ✓
- Referred to as work hardening. ✓

(4)**9.4 Effects of welding speed on distortion:**

- Increase in welding speed increases distortion due to larger flame
in oxy-acetylene welding. ✓
- Larger diameter electrode requires increased current causing more
localised heat. ✓
- Causing more residual stress. ✓
- Causing more distortion. ✓

(Any 3 x 1) (3)

9.5 Quenching media:

- Water ✓
- Oil ✓
- Brine ✓
- Liquid salts ✓
- Sand ✓
- Air ✓
- Ash ✓
- Lime ✓
- Molten lead ✓
- Nitrogen air-infused air ✓

(Any 3 x 1) (3)**9.6 Reducing welding distortion:**

- Do not over-weld. ✓
- Intermittent welding. ✓
- Place welds near the neutral axis. ✓
- Use a few passes as possible. ✓
- Use back step welding. ✓
- Anticipate the shrinkage forces. ✓
- Use clamps, jigs and fixtures. ✓
- Use strongbacks. ✓
- Heating metal before welding. (pre- heating) ✓
- Slowing the cooling rate ✓

(Any 3 x 1) (3)
[18]

QUESTION 10: MAINTENANCE (SPECIFIC)**10.1 Locking out of machine:**

- Isolation switches must be switched off. ✓
- The only key to the lock is in possession of the person carrying out the maintenance / Each maintenance person must have own lock. ✓

(2)

10.2 Tagging plates:

More than one technician can lock out machine simultaneously. ✓

(1)

10.3 Minor service for a power-driven guillotine:

The minor service is designed to minimise ✓ major mechanical and electrical failures. ✓

(2)

10.4 Cutting fluid:

- Keep the blade cool. ✓
- Keep the work piece cool ✓
- Prolong the life span of the blade ✓
- Washes cuttings away ✓
- Improves cutting efficiency ✓
- Reduces friction during cutting process. ✓
- Better finish given to workpiece. ✓
- Also prevents further corrosion. ✓

(Any 2 x 1)

(2)

10.5 Overloading a rolling machine:

- Limit the life span of components ✓
- Can result in costly damage ✓
- Damage to bearings/bushes ✓
- Damage to gearbox ✓
- Damage to motor ✓

(Any 1 x 1)

(1)

[8]

QUESTION 11: TERMINOLOGY (DEVELOPMENTS) (SPECIFIC)**11.1 True length of AC:**

$$AC^2 = AB^2 + BC^2$$

$$\text{but } BC = \frac{90-50}{2} \checkmark$$

$$= \frac{40}{2}$$

$$= 20 \text{ mm } \checkmark$$

$$AC^2 = AB^2 + BC^2$$

$$= 50^2 + 20^2 \checkmark$$

$$AC = \sqrt{2500 + 400} \checkmark$$

$$= 53,85 \text{ mm } \checkmark$$

$$= 54 \text{ mm } \checkmark$$

(6)

11.2 Development:

Square/rectangle ✓ to round ✓ transformer / transition piece / on centre. ✓

(3)

11.3 Square to rectangle on centre hopper:**11.3.1 True length of A-1:**

$$A-1 = \sqrt{\overset{\checkmark}{200^2} + \overset{\checkmark}{130^2} + \overset{\checkmark}{500^2}}$$

$$= \sqrt{40000 + 16900 + 250000}$$

$$= \sqrt{306900}$$

$$= 553,99$$

$$= 554 \text{ mm } \checkmark$$

(4)

11.3.2 True length of C-2:

$$\begin{aligned}
 C-2 &= \sqrt{\overset{\checkmark}{470^2} + \overset{\checkmark}{200^2} + \overset{\checkmark}{500^2}} \\
 &= \sqrt{220900 + 40000 + 250000} \\
 &= \sqrt{510900} \\
 &= 714,77 \\
 &= 715 \text{ mm } \checkmark
 \end{aligned}
 \tag{4}$$

11.4 Hoppers:

11.4.1 Square to rectangle \checkmark hopper off centre \checkmark (2)

11.4.2 Square to square \checkmark hopper on centre \checkmark (2)

[21]**TOTAL: 200**